From: Robert Werner
To: Stephen Tzhone

Subject: San Jacinto River Waste Pits (06ZQ) - SN Ltr Site Description With Two Site Illustrations

Date: 06/29/2009 12:16 PM

Attachments: Letter - IPC - Special Notice Letter - 2009-06-24 - Enclosure 2 - Preliminary Boundary Illustration -- 2009-06-

<u>11.pdf</u>

Letter - IPC - Special Notice Letter - 2009-06-24 - Enclosure 3 - Landfill Ownership -- 2009-06-24.pdf

SITE BACKGROUND

The Site is located east of the City of Houston in Harris County in the State of Texas in the area where the Interstate Highway 10 Bridge (I-10) crosses over the San Jacinto River (see Enclosure 2). The Site's two separate land areas are located in an unincorporated area known as Channelview. The portion of the San Jacinto River that is located within the Site's boundaries is situated between two unincorporated areas known as Channelview and as Highlands. The Site itself has no specific street address.

The Site's land area is comprised of two separate tracts of land. Soil samples taken from the first tract have confirmed the presence certain hazardous materials, including dioxin. Information available to EPA indicates that soil at the second tract contains the same hazardous materials, including dioxin. The Site also includes river sediment in an area of the San Jacinto River that is suspected to be contaminated with certain hazardous materials, including dioxin, that might have migrated from the Site's two tracts. The EPA has evidence that indicates dioxin had been transported to the Site in waste paper mill sludge that had been released onto the Site's two tracts during the 1960's.

Both tracts are on the west side of the San Jacinto River. One tract (Tract 1) is on the north side of I-10. Virgil C. McGinnes Trustee, is the current owner of record for Tract 1 (see Enclosure 3). Tract 1 is an abandoned 20-acre tract of land that is adjacent to the west shore of the San Jacinto River and the north side of I-10. Three exposed abandoned waste disposal pits are located on Tract 1. The three abandoned waste pits cover an area that approximates 3.5 acres of Tract 1. Part of Tract 1, including the abandoned disposal pit area, is now below the adjacent San Jacinto River's water surface. The Site's second tract (Tract 2) is an 18.7-acre tract of land that is on the south side of I-10 and is between the San Jacinto River and the Old River. A concealed abandoned waste pit covers an area that approximates five or more acres of Tract 2. Tract 2 is now comprised of a 15.85-acre parcel and a 2.854-acre parcel. Musgrove Towing Service, Inc. is the current owner of record for the 15.85-acre parcel (see Enclosure 3). New Lost River, LLC. is the current owner of record for the 2.854-acre parcel (see Enclosure 3).

Samples collected in the disposal pits located north of I-10 and river sediments up and down river from these pits have dioxin concentrations as high as 70,000 parts per trillion. Sediments contaminated with high levels of dioxin have been found in the San Jacinto River for a distance of at least one-half mile downstream from the disposal pits.



Letter - IPC - Special Notice Letter - 2009-06-24 - Enclosure 2 - Preliminary Boundary Illustration -- 2009-06-11.pdf



Letter - IPC - Special Notice Letter - 2009-06-24 - Enclosure 3 - Landfill Ownership -- 2009-06-24.pdf